



USE INSTRUCTIONS


1. Failure to follow all instructions and limitations can seriously reduce the effectiveness of this respirator and could lead to illness, injury or death.
2. A properly selected respirator is essential. Before occupational use, the wearer must be trained by the employer in the correct use of the respirator in accordance with applicable safety and health standards.
3. This product does not supply oxygen. Use only in adequately ventilated areas containing sufficient oxygen to support life.
4. Discard the respirator and replace with a new one if:
 - A. excessive clogging of the respirator causes breathing difficulty
 - B. the respirator becomes damaged.
5. Leave the contaminated area if dizziness, irritation or other Distress occurs.
6. Keep respirators in the display box away from direct sunlight until use.
7. User' s must be fit tested prior to wearing this respirator either qualitatively or quantitatively according to 29CFR1910.134
8. Before wearing the mask, respirator users mask must check whether there is crack or spot around the welding spot .if yes, the mask must be discarded at once and can not be used again

USE LIMITATIONS

1. Do **NOT** use the respirator or enter or stay in a contaminated area under the following circumstances:
 - a. atmosphere contains less than 19.5% oxygen.
 - b. if you smell or taste a contaminant.
 - c. for protection against gases or vapors.
 - d. contaminants or their concentrations are unknown or immediately dangerous to life or health.
 - e. concentrations of contaminants exceed maximum use concentrations in applicable OSHA standards or applicable government regulations or 10 times the PEL (Permissible Exposure Limit), whichever is lower.
 - f. For sandblasting, paint-spray operations asbestos.
 - g. Use in explosive atmospheres.
2. Do **NOT** modify or misuse the respirator.
3. Do **NOT** use the respirator with facial hair or any other conditions that may prevent a good face-seal.

Donning & Fitting Instructions

1. Open the respirator with both hands
2. Cup the respirator firmly against your face with the nosepiece on the bridge of your nose.
3. Stretch and pull the lower headband over the head and position below your ears. Stretch and pull the top headband on the back of your head above your ears
4. Press plastic nosepiece to conform snugly around your nose.
5. Seal check:
 - To test the fit of a respirator without an exhalation valve, cup both hands over the respirator and exhale sharply.
 - To test the fit of a respirator with an exhalation valve, cup both hands over the mask and inhale sharply. A negative pressure should be detected inside the respirator.
 - If air flow is felt in the nose area, re-adjust/tighten the nose clip.
 - If air flow is felt around the edges of the respirator, re-position the respirator/head strap to achieve a better fit.
6. Change the mask immediately if breathing becomes difficult or mask becomes damaged or distorted.
7. Change the respirator if a proper face seal can not be achieved.
8. Careful observance of these instructions is an important step in safe respirator use.



1



2



3



4

Protection:

- N-series filters are effective against particle aerosols free of oil.

Guangzhou Harley Commodity Company Limited

Floor 1 to 4, #8, Team 17, Sandong Village, Xinhua Street,

Huadu District, Guangzhou 510800 CHINA

TEL: 0086-20-36928707

FAX: 0086-20-36928797